

12. The scale will go to zero.

**Span Calibration** Ver: 1.00, August 2006 Model: BK-Series Scales

## Span Calibration for BK-Series Scales

1.	Turn the scale ON and once the Weight Display shows the ROM version number, press the key.
2.	The displays will then show:
3.	Press $0$ , $0$ , $0$ , and then $\frac{1}{1}$ .
4.	The displays should look like this:
5.	Press the tare key and the displays will look like this:
6.	Make sure that there is nothing on the platter and that the platter and platform are correctly placed on the
7.	scale; then press the key.  The displays will then look like this for a 600 pound scale:
7.	LoAd 600 Pound5
8.	The 600 pound scale can be calibrated using 60, 120, 300, or 600 pounds; the 300 pound scale can be calibrated using 30, 60, 150, or 300 pounds; the 150 pound scale can be calibrated using 15, 30, 75, or 150 pounds; and the 120 pound scale can be calibrated using 12, 24, 60, or 120 pounds. At this point you must
	select the amount of weight you will use to calibrate the scale with by using the key (Speed Key 4) to toggle between 100%, 10%, 20%, or 50% of scale capacity.
	When you have selected the amount of weight you wish to use, place it on the platter and press (TARE).
10.	The display will show the following for exactly 3 seconds:
11.	Remove the weight from the platter and press the key.

If further problems persist, please contact the Atron Systems Service Department at 973-227-8882.

www.atronsystems.com © 2006, All rights reserved.